Weatherization Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0935/1

Work Order Type: Weatherization

Audit Name: 17017UC-0935

CLIENT INFORMATION

Client ID: 17017UC-0935

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Fax:

Address: 3313 Williams Enterprise Drive

Cookeville, TN 38506 Email Address:

Company Name & License Number	er:	
Contractor's Signature:		

COMMENT

mobile home 1056 sq ft. built 1992

	Measure 1 Sea	Ducts			Componen	ts			Inspected
C	omment Ducts:								
	seal off	registers #3 and #5 initial	pressure	readin	_				
					Estimated	· 		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Duct sealing (setup cost)	Each	1					
10	Miscellaneous Supplies	Duct Sealing	Each	1					
C	other Detail							<u> </u>	
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	foam ins		panel off				und	,	Inspected
			,		Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
c	Other Detail								
_				Measur	e Sub Total:			Sub Total:	
Г									
	Field Notes:							_	

ı	Measure 3 DW	H Tank Insulation			Componen	ts		1	nspected
C	Comment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Tank Insulation	Each	1					
2	Labor	DWH Tank Insulation	Each	1					
C	Other Detail						,		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 4 DW	H Pipe Insulation			Componen	ts		ı	Inspected
		H Pipe Insulation			Componen Estimated			Actual	Inspected
C		H Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspected
<i>C</i>	Comment	•	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C #	Comment Material / Labor	Description / Comment		_	Estimated		Qty	Actual	
C # 1	Comment Material / Labor Insulation	Description / Comment DWH Pipe Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Insulation Labor	Description / Comment DWH Pipe Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Insulation Labor	Description / Comment DWH Pipe Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Insulation Labor	Description / Comment DWH Pipe Insulation	Each Each	1 1	Estimated			Actual	
C # 1	Material / Labor Insulation Labor	Description / Comment DWH Pipe Insulation	Each Each	1 1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Material / Labor Insulation Labor Other Detail	Description / Comment DWH Pipe Insulation	Each Each	1 1	Estimated Unit Cost			Actual Unit Cost	

Comment bid as a tun	k [heating]			Componen	ts			Inspecte
Comment bla as a tan	ne up.							
				Estimated	1		Actual	
# Material / Labor De	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Se Equipment	etback thermostat	Each	1					
2 Labor Se	etback thermostat	Each	1					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
	sture Problems			Componen	ts			Inspecte
	sture Problems nent/Crawlspace) 105	6 sq. ft		Componen	ts			Inspecte
(Basem		6 sq. ft		Componen Estimated			Actual	Inspecte
(Basem Comment		6 sq. ft <i>Unit</i> s	Qty			Qty		Inspecte
(Basem Comment # Material / Labor De	ent/CrawIspace) 105			Estimated	,	Qty	Actual	
(Basem Comment # Material / Labor De Health and Safety Me Items	ent/CrawIspace) 105	Units	Qty	Estimated	,	Qty	Actual	
(Basem Comment # Material / Labor De Health and Safety Me Items	nent/CrawIspace) 105 escription / Comment oisture Barrier Needed	<i>Units</i> SqFt	Qty 1056	Estimated	,	Qty	Actual	
(Basem Comment # Material / Labor De Health and Safety Me Items Labor La	nent/CrawIspace) 105 escription / Comment oisture Barrier Needed	<i>Units</i> SqFt	Qty 1056	Estimated	,	Qty	Actual	
(Basem Comment # Material / Labor De Health and Safety Me Items Labor La	nent/CrawIspace) 105 escription / Comment oisture Barrier Needed	<i>Units</i> SqFt	Qty 1056	Estimated	,	Qty	Actual	
(Basem Comment # Material / Labor De Health and Safety Me Items Labor La	nent/CrawIspace) 105 escription / Comment oisture Barrier Needed	<i>Units</i> SqFt	Qty 1056	Estimated	,		Actual	

Measure 7 Smoke Detector is Needed				Componen		Inspected			
C	comment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	9-volt Smoke Detector	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						,		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	